U.S. DEPARTMENT OF LABOR
Occupational Safety and Health Administration

Form Approved OMB No. 44-R1387

MATERIAL SAFETY DATA SHEET

MAY 24 1982

Required under USDL Safety and Health Regulations for Ship Repairing,
Shipbuilding, and Shipbreaking (29 CFR 1915, 1916, 1917)

		SECT	ION I		
MANUFACTURER'S NAME			EMERGENCY TELEPH	IONE NO	•
STABOND CORPORATION			(213) 770-0	591	
ADDRESS (Number, Street City State, and ZIP Co		GARDEI	NA, CA. 90249		
CHEMICAL NAME AND SYNONYMS NEOPRENE CONTACT CEMENT		•	TRADE NAME AND SYNSXYMS	(DAC#	[⊈] D PM 3
CHEMICAL FAMILY NA			FORMULA NA	•	
SECTION	11 -	HAZAF	RDOUS INGREDIENTS		
PAINTS, PRESERVATIVES, & SOLVENTS	%	TLV (Units)	ALLOYS AND METALLIC COATINGS	%	TLV (Units)
PIGMENTS			BASE METAL		
CATALYST			ALLOYS		
VEHICLE .			METALLIC COATINGS		'
SOLVENTS	80		FILLER METAL PLUS COATING OR CORE FLUX		
ADDITIVES			OTHERS		
OTHERS					
HAZARDOUS MIXTURES OF OTHER LIQUIDS, SOLIDS, OR GASES					TLV (Units)
(SOLVENT BLEND-TOLUENE, ACETONE, HEXANE) TOLUENE				IE 18	3 100 I
			ACETON	IE 19	1000
•			HEXANE	53	3 500 I
		, , , ,			
SEC	TIO	N III - F	PHYSICAL DATA		
BOILING POINT (°F.)		135	SPECIFIC GRAVITY (H2O=1) APPRO	X (0.8
VAPOR PRESSURE (mm Hg.)		180	PERCENT, VOLATILE BY VOLUME (%) APPRO		0.85
VAPOR DENSITY (AIR=1) APPROX.		3.0	EVAPORATION RATE (NBU O AC =1)		5-1.5
SOLUBILITY IN WATER APPROX.		8%	(SOLVENT ONLY)		
			RGANIC HYDROCARBON ODOR		<u> </u>
SECTION IV -	FIR	L AND I	EXPLOSION HAZARD DATA		Liet
FLACTI POINT (Method used) 0°F. (T.C			FLAMMABLE LIMITS Le 1.2	Jakaniskia van	10.0 I
EXTINGUISHING MEDIA CO, FOAM	OR	DRY (CHEMICAL		
SPECIAL FIRE FIGHTING PROCESURES					
HANDLE AS FLAMMABLE H	YDR	OCARBO	ON LIQUID IN WET STATE		
UNUSUAL FIRE AND EXPLOSION HAZARDS					

SECTION V - HEALTH HAZARD DATA	
THRESHOLD LIMIT VALUE 100 PPM (TOLUENE)	
EFFECTS OF OVEREXPOSURE	
HEADACHE, NAUSEA, IMPAIRMENT OF COODINATION, INTOXICATION,	NARCOSIS
EMERGENCY AND FIRST AID PROCEDURES	,
REMOVE FROM EXPOSURE, LOOSEN ANY TIGHT CLOTHING. APPLY ART	IFICAL
RESPIRATION IF UNCONSCIOUS	

SECTION VI - REACTIVITY DATA								
STABILITY	UNSTA	CONDITIONS TO AVOID						
	STABLE	TABLE X						
INCOMPATABILITY (Materials to avoid)								
HAZ BROUFILM MAY RELEASE TOXIC GASES DURING COMBUSTION								
HAZARDOUS MAY OCCUR				CONDITIONS			,	
POLYMERIZATION		WILL NOT OCCUR		X				

SECTION VII - SPILL OR LEAK PROCEDURES				
STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED				
SOAK UP WITH ABSORBENT MATERIAL				
WASTE DISPOSAL METHOD				
BURY IN CLOSED CONTAINER				

· · · · · · · · · · · · · · · · · · ·			FORMATION		
	SECTION VIII - SPECIAL P	ROTECTION IN	FORMA HON		
	<u>·</u>				
RESPIRATOR	WITH ACTIVATED CHARCOAL	FILTER FOR	EXTENDED	VAPOR	EXPOSURE
VENTILATION	USE ONLY IN WELL VENTII	LATED AREAS	SPECIAL		
w	RECHANICAN LARGE SURFACE	APPLICATIO	OTHER NS	Deligings seeker in a mercilina	. Na santa a santa sa
RECOMMENDE	'ES ,	EYE PROTECTION RECOMM			¥
OTHER PROTECTIV	E EQUIPMENT		The second secon		

SECTION IX - SPECIAL PRECAUTIONS
PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING DO NOT STORE NEAR HEATING EQUIPMENT
STORE AS FLAMMABLE LIQUID
DO NOT EXPOSE VAPORS TO OPEN FLAME, SPARKS OR NON-EXPLOSION PROOF
ELECTRICAL EQUIPMENT.

GPO 934-110